


The header banner features a blue sky background with a white wireframe structure resembling a bridge or aircraft wing spanning across it. On the left, there are two 3D models: one of a vertical component on a base and another of a horizontal component. On the right, there are two more 3D models: a vertical component with circular cutouts and a horizontal component, both showing stress distribution with a color gradient from blue to red.

# StressCheck 12.1 Documentation

## StressCheck Toolbar Guide


In this document, a snapshot of each toolbar and its associated icons is provided.  
For a full description of the StressCheck GUI, refer to [GUI Standards & Layout Overview](#).



# Main toolbar



STRESSCHECK®




For more details, refer to the [Main Toolbar Overview](#).

# Attributes toolbar



STRESSCHECK®




For more details, refer to the [Attributes Toolbar Overview](#).

# Display Options toolbar



STRESSCHECK®



For more details, refer to the [Display Options Toolbar Overview](#).



The diagram illustrates the View toolbar with the following icons and their functions:

- Translate (t)**: Icon showing a cube with arrows indicating movement.
- Center Rotate**: Icon showing a cube with a circular arrow around it.
- Rotate (r)**: Icon showing a cube with a circular arrow around it.
- Zoom (z)**: Icon showing a magnifying glass with a plus sign.
- Box Zoom (b)**: Icon showing a magnifying glass with a plus sign and a dashed box.
- Camera/Lighting**: Icon showing a camera and a light source.
- Window Layout**: Icon showing a window with a yellow background.
- Restored Saved View (D)**: Icon showing a cube with a red arrow pointing to a saved view.
- Save View (V)**: Icon showing a cube with a red arrow pointing to a saved view.
- Center Visible Elements**: Icon showing a cube with a blue crosshair.
- Center Model (c)**: Icon showing a red cube.


The **View Selector** is a vertical list of view icons on the left side of the toolbar, highlighted with a red box. It includes icons for different view types (isometric, perspective, etc.) and a refresh icon at the bottom.

© 2025 ESRD, Inc. All Rights Reserved. StressCheck® is a registered trademark of ESRD, Inc.

# Display Objects toolbar



STRESSCHECK®




For more details, refer to the [Display Objects Toolbar Overview](#).

# Edit toolbar



STRESSCHECK®



For more details, refer to the [Edit Toolbar Overview](#).